

PUBLIC WORKS DEPARTMENT (BUILDING & ROADS) DARYANA

Procurive Engineer, Procurint Division No. 2 PWD B&R Br. Karnat

Tele Last: 0184-2220946 F. mail ID- psd-eepd2 kanal@hty-to- m

10

Subject:

The Principal, **PM Shri** Govt. Senior Secondary School, Padhana District Karnal

Memo No. 528

Dated: 03-04-25

Issue of Building Safety Certificate.... PM Shri Govt. Senior Senior Senior

Reference: Your letter No. 03 dated: 01.04.2025

The subject cited building has been inspected by the Sub Divisional Engineer alor with Junior Engineer and based on visual inspection it is reported that the building appears to 3 safe. The same be periodically maintained to keep it in serviceable condition for the intended perio-This certificate is valid for one year from the date of issue.

DA/Annexure

Endst. No.

Dated:

Copy forwarded to the Sub Divisional Engineer, Provincial Sub Division No.1, PWD B& Br. Karnal for information and necessary action.

DA/Nil

دم ' Executive Engineer, Provincial Division No.2, PWD B&R Br. Karnal.

Executive Engineer, Provincial Division No.2, PWD B&R Br. Karnal.

## BUILDING SAFETY CERTIFICATE

## NO.

## Dated:-

Certified that the existing building of P.M. Shri Govt. Senior Secondary School (name of the building or premises) at Padhana (Karnal) (address) is having blocks (s) Floor (s) as per detail below:-

Detail of Blocks(s) (in school)	Block (i)	Block (ii)	Block (iii)	Block (iv)	Block (v)	Block (vi)	
No. of Floor	G1+1						
(s) in the							
Block							

- 1. Building seems to be safe as per its physical appearance.
- 2. Building is periodically maintained to keep it serviceable for the intended period.
- 3. The school building may be considered as safe for public use in general condition.
- Building Safety Certificate issued only for one year from the date of issue of this certificate. Issued on ......by

al Sub Division No. W.D. B&R Br. Karnal

Signature with Seal Name: Designation:

Name & Address of Department / office